



Bulletin No. REL-JD1.32-2 Group No. 1.30

February 21, 2005

Page 1 of 1

NAR-57241 Vibration Damper.

Reliance Parts Corporation is pleased to announce the addition of vibration damper part number NAR-57241.

Shown below are the machine and engine applications for this new vibration damper:

MACHINE MODEL	ENGINE MODEL & SERIAL NO.
690B Excavator	6-404T S/N 335,846 and up
4040 Farm Tractor	6-404D S/N 335,846 and up
4240 Farm Tractor	6-466D
4230 Farm Tractor	6-404D S/N 335,846 and up
4320 Farm Tractor	6-404T S/N up to 335,845
4350 Farm Tractor	6-466T
4430 Farm Tractor	6-404T S/N 335,846 and up
4440 Farm Tractor	6-466T S/N up to 253,372
4455 Farm Tractor	6-466T
6600 Combine	6-404T S/N 335,846 and up
6602 Combine	6-404T / 6-466T
6620 Combine	6-466D,T
6622 Combine	6-466T S/N 253,373 and up
7700 Combine	6-404T S/N 335,846 and up
7720 Combine	6-466T

It is strongly recommended that these vibration dampers be replaced every 3,000 hours and during engine overhaul. Failure to replace worn or damaged vibration dampers may result in crankshaft breakage and related damage. Pricing information is available in the price list.

Be sure to add this popular vibration damper to your next order.